

Levellogger®


Model 3001

Using Your Levellogger NPT Adaptor (#108549)

Note: The Levellogger NPT Adaptor is not recommended for pressures in excess of 30 psi. (66 ft. (20 m) of water column).

1. The compression fitting nut may have to be loosened before the Levellogger is inserted.
2. Slide the Levellogger into the Compression Fitting, leaving approximately 1/4" of Levellogger body exposed above the Compression Fitting.
3. Tighten the Nut 1-1/4 turns past finger tight for a proper seal.
4. Thread the 1/4" NPT Connector into a Female NPT connection until finger tight.

Note: To connect a Solinst Direct Read Cable and/or a Levellogger, simply unthread the Top Cap of the Levellogger and thread on the Connector Cable.



*NPT Adaptor with Levellogger Installed
and Connection to Direct Read Cable*



*NPT Adaptor
with Levellogger Installed*

®Solinst is a registered trademark of Solinst Canada Ltd.

Printed in Canada
July 25, 2011
(#108550)

For further information contact: Solinst Canada Ltd.
Fax: +1 (905) 873-1992; (800) 516-9081 Tel: +1 (905) 873-2255; (800) 661-2023
35 Todd Road, Georgetown, Ontario Canada L7G 4R8
Web Site: www.solinst.com E-mail: instruments@solinst.com

Solinst®